

Air Condition Rate Card

Visitation Fee Charges Applied At 299 per Service

&

Conveyance Charges are Applied At ₹ 199 per Appliance

All prices below include the cost of spare parts, sourcing, and partner conveyance. Please pay only ₹199 for conveyance; no extra amount is required.

Electrical Parts Rate Card

Description	Service Charges ₹
Non-Inverter PCB Repaired	1199 + Conveyance + Visitation Fee
Inverter PCB	3999 + Conveyance + Visitation Fee
Replace LVT Low Voltage Thermostat Ac/Dc	7991199 + Conveyance + Visitation Fee
Replace Sensor Inverter/Non-Inverter	350/550 + Conveyance + Visitation Fee
Contactor Replaced (Signal Poll)	699 + Conveyance + Visitation Fee
Contactor Replaced Daikin/O-General	1299 + Conveyance + Visitation Fee
Convert Normal To Pcb With Handset	1499 + Conveyance + Visitation Fee

Fan Capacitor 1.0 To 6 Mfd	199 + Conveyance + Visitation Fee
Fan Capacitor 8 To 10	299 + Conveyance + Visitation Fee
Compressor Capacitor 25 To 60	599 + Conveyance + Visitation Fee
Compressor & Fan Motor Capacitor Combo	699 + Conveyance + Visitation Fee
Inverter Ac Pcb Refurbish/ New	7599/9599 + Conveyance + Visitation Fee

Gas Charging Rate Card

Description	Service Charges ₹
Gas Charging R –22	1950 + Visitation Fee
Gas Charging R – 32 & R 410 A	2250 + Visitation Fee
Leak Testing + Vacuum + Blazing	799

Rate Card

Copper coil condenser 1.5-ton split (Outdoor)	4599 + Conveyance + Visitation Fee
Copper coil condenser 2-ton split (Outdoor)	5599 + Conveyance + Visitation Fee
Copper cooling coil 1.0-ton split (Outdoor)	3599 + Conveyance + Visitation Fee
Capillary and filter replaced	399
Compressor 0.8 - 1 ton	7599 + Conveyance + Visitation Fee
Compressor 1.5 ton	8599 + Conveyance + Visitation Fee
Compressor 2 ton	9799 + Conveyance + Visitation Fee
Expansion valve replaced	1399 + Conveyance + Visitation Fee
Copper cooling coil/condenser coil (window AC)	4599/6599 + Conveyance + Visitation Fee
Replacement compressor (1 ton) R-22 / (R-32/410)	3899/4899 + Conveyance + Visitation Fee
Replacement compressor (1.5 ton) R-22 / (R-32/410)	4899/5899 + Conveyance + Visitation Fee
Replacement compressor (2 ton) R -22 / (R-32/410)	5999/7299 + Conveyance + Visitation Fee

Service valve replaced - 1/4	399 + Conveyance + Visitation Fee
Service valve replaced - 1/2	499 + Conveyance + Visitation Fee
Service valve replaced - 5/8	599 + Conveyance + Visitation Fee
Copper cooling coil (split AC) - 1 ton (Indoor Unit) R 22 / R32 / R 410	5299 + Conveyance + Visitation Fee
Copper cooling coil (split AC) 1.5-ton (Indoor Unit) R 22 / R 32 / R 410	6299 + Conveyance + Visitation Fee
Copper cooling coil (split AC) - 2 ton (Indoor Unit) R 22 / R32 / R 410	7299 + Conveyance + Visitation Fee
Copper cooling coil (split AC) O general & Mitsubishi - 1.5 ton (indoor unit) R 22 / R 32 / 410	7800 + Conveyance + Visitation Fee

Rate Card

Copper cooling coil / condenser coil (window AC) -2 ton	5299/6599 + Conveyance + Visitation Fee
Fuse Change In PCB	199 + Visitation Fee
Cooling coil Repair with Anti Rust Coating	899 + Conveyance + Visitation Fee
Anti Rust Coating for All Type of Ac	799 + Conveyance

Fan Motor Rate Card

Fan motor – split AC (Out Door) Ac / Dc	1499 / 2499 + Conveyance + Visitation Fee
Blower motor – split AC Indoor Ac / Dc	2199 / 3499 + Conveyance + Visitation Fee
Blower replaced Window / Indoor Unit	1199 / 1699 + Conveyance + Visitation Fee
Replace flap/swing moto	299 + Conveyance + Visitation Fee
Motor bearing change	899 + Conveyance + Visitation Fee
Fan motor – window AC	2499 + Conveyance + Visitation Fee
Noise issue repair	1+ Visitation Fee

Installation Rate Card

Description	Service charge ₹
1 meter copper pipe set China (with insulation, wire light)	899 (Conveyance on Bulk)
1 meter copper pipe set India (with insulation, wire Medium)	1099 (Conveyance on Bulk)

1 meter copper pipe set Malaysia (with insulation, wire Heavy)	1199 (Conveyance on Bulk)
1 meter copper pipe set Heavy (with insulation, wire Heavy)	1299 (Conveyance on Bulk)
Indoor unit reinstalled	699 + Visitation Fee
Fastener complete set	199
Floor stand	699 + Conveyance
Universal back plate	299 + Conveyance
Foam-jet AC service	499
AC installation Window Without Wood	499
AC uninstallation Window	299
Anti – rust spray (avoid gas leak)	899 + Conveyance
Lite AC service	399
AC uninstallation Spilt Type	699
Ac Installation Spilt Type	1499

Rate Card

Description	Service charge ₹
Water leakage repaired – split AC	99 + Visitation Fee
Adjust grill locks	1+ Visitation Fee
Adjust pipe and tight compressor screw	1+ Visitation Fee
Connector wires replaced (1m)	99 + Visitation Fee
Tighten/ replace thimble	99 + Visitation Fee

Rate Card

Drain pipe adjust	1 + Visitation Fee
Noise adjustment in motor	1 + Visitation Fee
Noise adjustment in blower	1 + Visitation Fee
Noise adjustment in cabinet	1 + Visitation Fee
Noise adjustment in swing flap	1 + Visitation Fee

Water leakage repaired- window AC	1 + Visitation Fee
-----------------------------------	--------------------

Rate Card

Description	Service charge ₹
AC fan blade Window / Spilt Outdoor	699 / 799 + Conveyance + Visitation Fee
Grill cover (Window)	1599 + Conveyance + Visitation Fee
Swing blade replaced	399 + Conveyance + Visitation Fee
Universal remote	499 + Conveyance + Visitation Fee
Water tray	499 + Conveyance + Visitation Fee

Rate Card

Drain pipe adjust	99 + Visitation Fee
Insulation refixes	99 + Visitation Fee
Noise issue repair	1 + Visitation Fee
Stabilizer connection	1 + Visitation Fee

New Indoor & Outdoor Rate Card

Description	Service charge ₹ (Actual price at time of installation)
Jobu (Diken) Indoor 1.5 ton	14299 + Conveyance
Raque (Hitachi) Indoor 1.5 ton	11599 + Conveyance
Godrej Indoor 1.5 ton	11299 + Conveyance
Jobu (Diken) Indoor 1.8 ton	17599 + Conveyance
Raque (Hitachi) Indoor 2.0 ton	14599 + Conveyance
Godrej Indoor 2.0 ton	14299 + Conveyance
Sakoda Outdoor 1.5 ton (without Compressor & Accessories)	8599 + Conveyance
Sakoda Outdoor 2.0 ton (without Compressor & Accessories)	11599 + Conveyance
Speed Outdoor 1.5 ton (without Compressor & Accessories)	10299 + Conveyance
Speed Outdoor 2.0 ton (without Compressor & Accessories)	13599 + Conveyance

Labour Charges Only – Material Not Included

Air Condition Rate Card

Description	Service charge ₹
Stabilizer Fitting	299
Power Problem	299
Capacitor Installation / uninstallation	399
Pcb Installation / uninstallation	399
Fan Motor uninstallation	499
Fan Motor installation	799
Fan & Blower Uninstallation	399
Fan & Blower Installation	699
Cooling & Condenser Coil Uninstallation	599

Cooling & Condenser Coil Installation	599
Leak Testing + Blazing	399
Gas Charging	799
Compressor uninstallation	499
Compressor Installation & Gas Charging	1199

Air Condition Cooper Piping Rate Card

Description	Service charge ₹
China Cooper + Insulation Foam + Venial Tape + Light Wire (Company) + Drain Pipe 20 mm + Zeri + Clamping + Visitation Fee+ Cattage	850 (Conveyance on Bulk order)
China Cooper + Insulation Foam + Venial Tape + Medium Wire (Company) + Drain Pipe 25 mm + Zeri + Clamping + Visitation Fee+ Cattage	875 (Conveyance on Bulk order)
China Cooper + Insulation Foam + Venial Tape + Heavy Wire (Company) + Drain Pipe 25 mm + Zeri + Clamping + Visitation Fee+ Cattage	899 (Conveyance on Bulk order)
Indian Cooper + Insulation Foam + Venial Tape + Light Wire (Company) + Drain Pipe 20 mm + Zeri + Clamping + Visitation Fee+ Cattage	870 (Conveyance on Bulk order)
Indian Cooper + Insulation Foam + Venial Tape + Medium Wire (Company) + Drain	899 (Conveyance on Bulk order)

Pipe 25 mm + Zeri + Clamping + Visitation Fee+ Cattage	
Indian Cooper + Insulation Foam + Venial Tape + Heavy Wire (Company) + Drain Pipe 25 mm + Zeri + Clamping + Visitation Fee+ Cattage	985 (Conveyance on Bulk order)
Malaysia Cooper + Insulation Foam + Venial Tape + Light Wire (Company) + Drain Pipe 20 mm + Zeri + Clamping + Visitation Fee+ Cattage	925 (Conveyance on Bulk order)
Malaysia Cooper + Insulation Foam + Venial Tape + Medium Wire (Company) + Drain Pipe 25 mm + Clamping + Visitation Fee+ Cattage	975 (Conveyance on Bulk order)
Malaysia Cooper + Insulation Foam + Venial Tape + Heavy Wire (Company) + Drain Pipe 25 mm + Zeri + Clamping + Visitation Fee+ Cattage	999 (Conveyance on Bulk order)
Mandav Cooper + Insulation Foam + Venial Tape + Medium Wire (Company) + Drain Pipe 25 mm + Zeri + Clamping + Visitation Fee+ Cattage	1099 (Conveyance on Bulk order)
Mandav Cooper + Insulation Foam + Venial Tape + Heavy Wire (Company) + Drain Pipe 25 mm + Zeri + Clamping + Visitation Fee+ Cattage	1199 (Conveyance on Bulk order)
Mandav (Heavy) Cooper + Insulation Foam + Venial Tape + Heavy Wire (Company) + Drain Pipe 25 mm + Zeri + Clamping + Visitation Fee+ Cattage	1299 (Conveyance on Bulk order)
Without Any Material or Zeri Only Labour Charges	240/mtr.
Site Inspection Charges for Piping	399

Note

1. *The amount you pay at booking is a visitation fee which will be adjusted in your final installation quote.*

2. If spare parts are needed, the technician will source them from the local market, and cartage charges will be applied.
3. How many days of warranty are written on the bill by the company & technician after the work is completed
4. **No Hidden Charges**

Please Note



If spare parts are needed, the Technician will source them from the local market



Our Installation process

1. Inspection

We will check the space where you want to install the Appliances

2. Installation

We will install the appliances with care

3. Cleanup

We will clean the area once work is done



REPAIR SERVICE

Our Repairing & Services Process

1. Inspection & quote

We inspect the appliance & share a repair quote for approval

2. Approval or expert review

Repair begins after your approval, if you are unsure, you can call our expert

3. Service, Repair & spare parts

If necessary, we will provide spare parts at fixed rates during the repair & service.

4. Warranty activation

Your appliance will automatically come under warranty Period after the repair

Given by Technician/Company on time of billing



Souned Promise



Up to 10 to 365 days warranty on different product & services



Fixed Rate Card



On Call Repair Quote Verification



Up to 3000 Damage Cover



*Surprise Checking/Feedback at the time or after the work by **Senior technicians***

Our Top Technicians



*Background Verified by **Souneds***



*Trained across all major brands by
Souneds Experianesd Techinitions*

What we'll need from you

- *Buckets*
- *Point*
- *Ladder / Stool*
- *Clean Cloth*

What We Will Do and Not Do on the Work Site For The Service Of Unit

- *Applicable For Both Spilt & Window Acs*
- *Camical / Foam & Jet Cleaning of Indoor With Gaket*
- *Jet Spray Cleaning of Outdoor only*

For Leakage Unit

- *Additional Charges Apply For More Then 2 Leaks*
- *Cooling Coil Repair Includes Anti Rust Coating To Extand The Ac Life.*
- *We Don't Repair Centralized Acs & Vrv System On Domestic Compland*

For Installation Not Included

- Cost of wiring will be charged extra
- Masonry / core cutting is not included

What's Included

- *Installation of outdoor & indoor with piping 10 ft only*
- *After 10 ft charged Rs – 200/mtr extra.*